

GROUP TECHNOLOGY

Overview of Group Technology (GT)


- Parts in the medium production quantity range are usually made in batches
- Disadvantages of batch production:
 - Downtime for changeovers
 - High inventory carrying costs
- GT minimizes these disadvantages by recognizing that although the parts are different, there are groups of parts that possess similarities
- GT exploits the part similarities by utilizing similar processes and tooling to produce them
- GT can be implemented by manual or automated techniques
- When automated, the term *flexible manufacturing system* is often applied

Group Technology Defined


- An approach to manufacturing in which similar parts are identified and grouped together in order to take advantage of their similarities in design and production
- Similarities among parts permit them to be classified into part families
- In each part family, processing steps are similar
- The improvement is typically achieved by organizing the production facilities into manufacturing cells that specialize in production of certain part families

Part Family

- A group of parts that possess similarities in geometric shape and size, or in the processing steps used in their manufacture
- Part families are a central feature of group technology
- There are always differences among parts in a family
- But the similarities are close enough that the parts can be grouped into the same family



-
-
- Two parts that are identical in shape and size but quite different in manufacturing:
 - (a) 1,000,000 units/yr, tolerance = ± 0.010 inch, 1015 CR steel, nickel plate
 - (b) 100/yr, tolerance = ± 0.001 inch, 18-8 stainless steel



- Ten parts that are different in size and shape, but quite similar in terms of manufacturing
- All parts are machined from cylindrical stock by turning; some parts require drilling and/or milling

Ways to Identify Part Families

1. *Visual inspection* - using best judgment to group parts into appropriate families, based on the parts or photos of the parts

2. *Production flow analysis* - using information contained on route sheets to classify parts

3. *Parts classification and coding* - identifying similarities and differences among parts and relating them by means of a coding scheme

Parts Classification and Coding

- Most classification and coding systems are one of the following:
 - Systems based on part design attributes
 - Systems based on part manufacturing attributes
 - Systems based on both design and manufacturing attributes

Part Design Attributes

- Major dimensions
- Basic external shape
- Basic internal shape
- Length/diameter ratio
- Material type
- Part function
- Tolerances
- Surface finish

Part Manufacturing Attributes

- Major process
- Operation sequence
- Batch size
- Annual production

- Machine tools
- Cutting tools
- Material type

Three structures used in classification and coding schemes

- Hierarchical structure, known as a mono-code, in which the interpretation of each successive symbol depends on the value of the preceding symbols
- Chain-type structure, known as a polycode, in which the interpretation of each symbol in the sequence is always the same; it does not depend on the value of preceding symbols
- Mixed-mode structure, which is a hybrid of the two previous codes


Some of the important systems

- Opitz classification system – the University of Aachen in Germany, nonproprietary, Chain type.
- Brisch System – (Brisch-Birn Inc.)
- CODE (Manufacturing Data System, Inc.)
- CUTPLAN (Metcut Associates)
- DCLASS (Brigham Young University)
- MultiClass (OIR: Organization for Industrial Research), hierarchical or decision-tree coding structure
- Part Analog System (Lovelace, Lawrence & Co., Inc.)

Basic Structure of the Opitz Parts Classification and Coding System

Digit	Description
1	Part shape class: rotation versus nonrotational (Figure 22.1). Rotational parts are classified by length-to-diameter ratio. Nonrotational parts by length, width, and thickness.
2	External shape features; various types are distinguished.
3	Rotational machining. This digit applies to internal shape features (e.g., holes, threads) on rotational parts, and general rotational shape features for nonrotational parts.
4	Plane machined surfaces (e.g., flats, slots).
5	Auxiliary holes, gear teeth, and other features.
6	Dimensions—overall size.
7	Work material (e.g., steel, cast iron, aluminum).
8	Original shape of raw material.
9	Accuracy requirements.

Basic structure of the Opitz system of parts classification and coding




Form code (digits 1-5) for rotational parts in the Opitz coding system

Digit 1		Digit 2		Digit 3		Digit 4		Digit 5	
Part class		External shape, external shape elements		Internal shape, internal shape elements		Plane surface machining		Auxiliary holes and gear teeth	
0 1 2 3 4 5 6 7 8 9 Rotational parts	$L/D \leq 0.5$	0 1 2 3 4 5 6 7 8 9 Nonrotational parts	Smooth, no shape elements	0 1 2 3 4 5 6 7 8 9 No hole, no breakthrough	No shape elements	0 1 2 3 4 5 6 7 8 9 No surface machining	No surface machining	0 1 2 3 4 5 6 7 8 9 No auxiliary hole	No auxiliary hole
	$0.5 < L/D < 3$		No shape elements		No shape elements		Surface plane and/or curved in one direction, external		Axial, not on pitch circle diameter
	$L/D \geq 3$		Thread		Thread		External plane surface related by graduation around the circle		Axial on pitch circle diameter
			Functional groove		Functional groove		External groove and/or slot		Radial, not on pitch circle diameter
			No shape elements		No shape elements		External spline (polygon)		Axial and/or radial and/or other direction
			Thread		Thread		External plane surface and/or slot, external spline		Axial and/or radial on PCD and/or other directions
	Functional groove	Functional groove	Internal plane surface and/or slot	Spur gear teeth					
	Functional cone	Functional cone	Internal spline (polygon)	Bevel gear teeth					
	Operating thread	Operating thread	Internal and external polygon, groove and/or slot	Other gear teeth					
	All others	All others	All others	All others					

Example 1: A part coded 20801

- 2 - Parts has L/D ratio ≥ 3
- 0 - No shape element (external shape elements)
- 8 - Operating thread
- 0 - No surface machining
- 1 - Part is axial

Example 2: given the part design shown define the "form code" using the Opitz system



Step 1: The total length of the part is 1.75, overall diameter 1.25,

L/D = 1.4 (code 1)


Step 2: External shape - a rotational part that is stepped on both with one thread (code 5)

Step 3: Internal shape - a through hole (code 1)

Step 4: By examining the drawing of the part (code 0)

Step 5: No auxiliary holes and gear teeth (code 0)

Code: 15100



Form code	6	5	4	4	3	6	0	7	0
Nonrotational, flat, A/B ≤ 3, A/C > 4	6								
Flat, small deviations from casting		5							
Main bores are parallel			4						
Plane stepped surface				4					
Drilling pattern for holes drilled in one direction					3				
Edge length A > 400 ≤ 600						6			
Matl.: Cast iron							0		
Internal form: Cast								7	
Surface finish: None									0


Square cast-iron flange classified by the Opitz system.

MultiClass – developed by the Organization for Industrial Research (OIR)


- First 18 digits of the Multiclass Classification and Coding System

Digit	Function
0	Code system prefix
1	Main shape category
2, 3	External and internal configuration
4	Machined secondary elements
5, 6	Functional descriptors
7-12	Dimensional data (length, diameter, etc.)
13	Tolerances
14, 15	Material chemistry
16	Raw material shape
17	Production quantity
18	Machined element orientation


MultiClass Coding System example – the rotational part design



MultiClass code number for the rotational part



Possible ambiguity with a coding system




Benefits of a Well-Designed Classification and Coding System

- Facilitates formation of part families
- Permits quick retrieval of part design drawings
- Reduces design duplication
- Promotes design standardization
- Improves cost estimating and cost accounting

- Facilitates NC part programming by allowing new parts to use the same part program as existing parts in the same family
- Computer-aided process planning (CAPP) becomes feasible

Composite Part Concept

- A *composite part* for a given family is a hypothetical part that includes all of the design and manufacturing attributes of the family
- In general, an individual part in the family will have some of the features of the family, but not all of them
- A production cell for the part family would consist of those machines required to make the composite part
- Such a cell would be able to produce any family member, by omitting operations corresponding to features not possessed by that part




- Composite part concept: (a) the composite part for a family of machined rotational parts, and (b) the individual features of the composite part

Composite Part Features and Corresponding Manufacturing Operations

Design feature	Corresponding operation
1.External cylinder	Turning
2.Face of cylinder	Facing
3.Cylindrical step	Turning
4.Smooth surface	External cylindrical grinding
5.Axial hole	Drilling
6.Counterbore	Counterboring
7.Internal threads	Tapping

Machine Cell Designs (Types of GT cells:)

- (a) Single machine
- (b) Multiple machines with manual handling
- (c) Multiple machines with mechanized handling
- (d) Flexible manufacturing cell
- (e) Flexible manufacturing system



Benefits of Group Technology

- Standardization of tooling, fixtures, and setups is encouraged
- Material handling is reduced
 - Parts are moved within a machine cell rather than entire factory
- Process planning and production scheduling are simplified
- Work-in-process and manufacturing lead time are reduced
- Improved worker satisfaction in a GT cell
- Higher quality work

Problems in Group Technology

- Identifying the part families (the biggest problem)
 - If the plant makes 10,000 different parts, reviewing all of the part drawings and grouping the parts into families is a substantial task
- Rearranging production machines in the plant into the appropriate machine cells
 - It takes time to plan and accomplish this rearrangement, and the machines are not producing during the changeover